

BUILDING FITNESS CERTIFICATE

1. Name of the Inspector
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

NEENA.P
SIRAJUL HUDA English medium School
Mulyangal Noched GP
RCL 4 storied with eight class size
each floor 6.1 x 6.10 x 3.5 m

5. Period for which the certificate is issued

2026-27

6. Nature of defects , if any

- a) Foundation and basement
- b) Superstructure
- c) Doors and Windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks, etc.)

Nil

7. Any major defects noticed which will render the building unsafe in any manner

No.

8. Whether maintenance works have been done properly

Yes.

9. Whether the structure is sound or not for conducting classes

Yes, the structure is sound for conducting under normal weather conditions.

CERTIFICATE

certified that the school building was inspected by me on 28/2/2026. and found to be fit / unfit to conduct classes, for the period 2026-27. for the reasons stated above.

Place:

Noched

PRINCIPAL

Date:

28/2/2026

Sirajul Huda English Medium School

MANAGER
Sirajul Huda English Medium School
Parambra, Chenoli P.O - 673525



Neena

Assistant Engineer
LID & EV Section
Noched Grama Panchayat

Engineer

